

ESSEX COUNTY - CONCENTRATED TORNADO DAMAGE AREAS



Prepared by the Essex County GIS Department
 202 South Church Lane
 P.O. Box 1079
 Tappahannock, VA 22560
 (804) 443-3490

Scale 1:10,000



DISCLAIMER: This map represents the damage that resulted from the February 24, 2016 tornado in Essex County. Information is current as of 1500 on March 2, 2016. This does not depict the entirety of the tornado path and damage assessments are still being done. Data portrayed on this map is for informational purposes only, and no guarantee of accuracy is made. This map will be updated as new information becomes available.

Source: Essex County GIS, Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AEX, Getmapping, Aerogrid, IGN, IGP, swisstopo, TIGER/Line, Timmons Group, NOAA and NWS.

LEGEND			
	Affected Habitable		Road Centerlines
	Minor Damage		Debris Staging Area
	Major Damage		Fire Department
	Destroyed		Tornado Path (NOAA)
	Command Post (Old Beale Church)		Concentrated Damage Areas (Residential)

